

# HISTORIC AMERICAN ENGINEERING RECORD

## INDEX TO PHOTOGRAPHS

Thompson Falls Hydroelectric Facility,  
Main Channel Dam  
Clark Fork River  
Thompson Falls  
Sanders County  
Montana

HAER No. MT-90-D

Documentation: 7 photographs (2008)  
2 photographic copies of original construction photos (1914)  
9 data pages

Kristi Hager, Photographer, August 2008

- MT-90-D-1      MAIN CHANNEL DAM. CONTEXT VIEW FROM SOUTH RIVER BANK ABOUT 300 FEET DOWNSTREAM OF DAM SHOWING WEST ABUTMENT, LOG SLUICE AND HOIST HOUSE (LEFT), SPILLWAY (CENTER), AND MODERN TAINTOR GATES (RIGHT). VIEW TO NORTH.
- MT-90-D-2      MAIN CHANNEL DAM. DOWNSTREAM FACE FROM EAST ABUTMENT SHOWING MODERN TAINTOR GATES (RIGHT FOREGROUND), SPILLWAY (RIGHT CENTER), AND LOG SLUICE, HOIST HOUSE AND WEST ABUTMENT WALL (RIGHT BACKGROUND). VIEW TO NORTHWEST.
- MT-90-D-3      MAIN CHANNEL DAM. WEST ABUTMENT WALL (LEFT CENTER), AND LOG SLUICE AND HOIST HOUSE (RIGHT CENTER). VIEW TO NORTH-NORTHEAST.
- MT-90-D-4      MAIN CHANNEL DAM. WEST ABUTMENT WALL. VIEW TO EAST.
- MT-90-D-5      MAIN CHANNEL DAM. EAST (RIVER) SIDE OF LOG SLUICE FROM CREST OF DAM. VIEW TO SOUTHWEST.
- MT-90-D-6      MAIN CHANNEL DAM. WEST (ISLAND) SIDE OF LOG SLUICE FROM CREST OF DAM. VIEW TO SOUTHEAST.

Thompson Falls Hydroelectric Project,  
Main Channel Dam  
HAER No. MT-90-D  
Index to Photographs, page 2

- MT-90-D-7      MAIN CHANNEL DAM. EAST FAÇADE OF HOIST HOUSE AT CREST OF DAM. NOTE HOIST ON CART BEHIND OPEN DOOR. VIEW TO WEST-NORTHWEST.
- MT-90-D-8      Photographic copy of original construction photo, December 19, 1914 (original print on file at PPL-Montana, Butte, Montana). CONTEXT VIEW OF MAIN CHANNEL DAM SHOWING WASTE GATE SECTION AND EAST HALF OF SPILLWAY WITH FRAMING ONLY (UPPER RIGHT) AND CONCRETE WORK IN PLACE AT WEST HALF OF SPILLWAY, LOG SLUICE AND WEST ABUTMENT WALL (UPPER LEFT). NOTE COFFER DAM IN RIVER CHANNEL BETWEEN EAST HALF AND WEST HALF OF SPILLWAY.
- MT-90-D-9      Photographic copy of original construction photo, December 19, 1914 (original print on file at PPL-Montana, Butte, Montana). DETAIL VIEW OF WEST HALF OF MAIN CHANNEL DAM SHOWING SPILLWAY (RIGHT FOREGROUND), AND LOG SLUICE AND WEST ABUTMENT WALL (CENTER BACKGROUND). NOTE COFFER DAM IN LOWER FOREGROUND.